

**Software Release Note
AT Version Vx40b
Class B GPRS Release**

1 New Features

None.

2 Corrected Problems (CP) / Changes in the AT command Description (AT)

Type	Title
CP	Bad encoding in LCP reject frame
CP	Missed SMS CB
CP	Problem with AGC control on packet idle channels
CP	Data transmission is interrupted
CP	AT&V2 : Wrong +IPR value (must be 115200 now)
CP	Bad parameter value in CLOSE DATA MODE v24_request
CP	Hplmn rescan timer restart whereas it should not
CP	Hplmn timer not restarted during a call
CP	Autobaud on What 4800-57600 and New TSRE It
CP	Bad management of number in international format for +CPBP command #10082
CP	CGREG: bad cgreg indication after changing mobile class
CP	EGSM channel 0 on the frequency hopping does not work
CP	V24 buffer problem doing a GPRS upload in mux mode
CP	The functioning of AT%Dn is not completely described and/nor implemented
CP	CGREG :5 is returned without any change in MT's GPRS network registration
CP	Unlock FD : at+clck=FD,0,PIN2 return OK before the end of treatment
CP	Pps session closed improperly in case of pap and no reply from the network
CP	AT+CPIN=<puk>,<pin_too_long>

3 Known Bugs

None.