wavecom

Software Release Note for Step 4

AT Version V534T

Update 19/02/03

New features

None

Corrected problems (CP) / Changes in the AT command interface (CAT)

☑ CP1- ST Flash memory correction

☑ CP2- 32K mode problem correction

Known bugs

As 534d software version

Design Features

As 534d software version