

**Software Release Note  
AT Version Vx40c  
Class B GPRS Release**

## 1 New Features

None.

## 2 Corrected Problems (CP) / Changes in the AT command Description (AT)

Type	Title
CP	delete entries in ME phonebook can corrupt the flash
CP	wbcm value incorrect just after init
CP	low voice issue due to numerical gain not set
CP	Missed SMS CB
CP	reset with sms over GPRS
CP	EF HPLMN can't be read with module/handset using SIM Phase 2+
CP	I2C bus desynchronized when reading data with MSB set to 1
CP	CGACT: bad error indication after AT+CGACT=1,1 when GPRS is not subscribed
CP	pps session closed improperly in case of pap and no reply from the network
CP	AT+CCFC=4,7,,,7
CP	AT+N5
CP	AT+COPS operator names formats
CP	Reset when sending SMS with +CGSMS=0 and CGATT=1

## 3 Known Bugs

Title
Backtrace with GM_CONFIG_REQ
Backtrace after RAU ACCEPT
Bad answer to AT+FRH=3 after end of page and lost of CARRIER