



Software Release Note

AT Version V534P

Update 28/01/03

Class B GPRS release

Features (from 534)

⇒ Same as 534

Corrected problems (CP) from 534 09gg

CP1- Flash memory correction

Known bugs

⇒ Same as 534

Design Features

⇒ Same as 534